

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS 1965 A

FOUNDATION REPORT

SMITHLAND DAM

OHIO RIVER

VOLUME II of II

PHOTOGRAPHS AND FOUNDATION MAPS

Contract No. DACW62-75-C-0015

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	AI25057	3. RECIPIENTO CATALO, NUMBER
4. TITLE (and Subtitle)		5. TYPE OF REPORT & HERIOD COVERED
Foundation Report		Dimul
Smithland Dam, Ohio River		Finn) 6. PERFORMING ORG. REPUF NUMBER
7. AUTHOR(e)		B. CONTRACT OR GRANT NUMBER'S;
Rick Schipp		
Bryan Moser		DACW62-75-C-0015
PERFORMING ORGANIZATION NAME AND ADDRES	S	10. PROGRAM ELEMENT PROJECT TASK AREA & WORK UNIT NUMBERS
U.S. Army Corps of Engineers Louisville District, Constructio	un Division	
P.O. Box 59. Louisville, Kentuck		
1. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
As Above		February 1983
AS ADOVE		13. NUMBER OF PAGES
4. MONITORING AGENCY NAME & ADDRESS(II dittere	mt from Controlling Office)	15. SECURITY CLASS (of this report)
•		
As Above		Unclassified
		158. DECLASSIFICATION DOWNGRADING SCHEDULE
6. DISTRIBUTION STATEMENT (of this Report)		
Approved for public release, dis	tribution unlimit	4
Approved for public release, dis	tribution unitmit	.ea.
7. DISTRIBUTION STATEMENT (of the abetract entered	in Block 20, if different fro	m Report)
8. SUPPLEMENTARY NOTES		W
St. 3. m. T. C. T.T.		
Volume I & II		
9. KEY WORDS (Continue on reverse side if necessary a	nd identify by block number)	
Navigation		•
Dam		
Ohio River Smithland, Kentucky		
Smithiand, Rentucky		
D. ABSTRACT (Continue on reverse side If necessary as	ed identify by block number)	
This report presents complete for		of conditions encountered

This report presents complete foundation records of conditions encountered during construction and the methods used to adapt the dam structures to these conditions. The report covers the construction of the Smithland Dam and Weir only. The construction for the twin 1200 foot locks is covered under a previous report. The high lift gated section of the dam consists of 12 piers and 11 gated bays. The dam section starts on the Kentucky side of the riverwall of the locks and extends 1400 feet to the Kentucky side of pier 12. A fixed weir consisting of granular filled and concrete capped \(\left(\cong \mathbf{con}'\) t over)

DD 1 JAN 79 1473 EDITION OF 1 NOV 65 IS DESOLETE

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

4 - 5 to 5 to 6 to 5

/ + **974** +

30

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered) ysteel piling cells extends from pier 12 some 1728 feet to the Kentucky bank.

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)

VOLUME II


SMITHLAND DAM

FOUNDATION REPORT

J. A. JONES CONSTRUCTION CO. & NELLO L. TEER COMPANY
(A JOINT VENTURE)

CONTRACT NO. DACW 62-75-C-0015





X

VOLUME II :

SMITHLAND DAM

FOUNDATION REPORT

INDEX

PART I - PHOTOGRAPHS .

Description	Photograph No.
Cutoff Trench	1 thru 17
Gate Bays, Stilling Basin	18 thru 36
Piers No. 1 through No. 12	37 thru 86

PART II - FOUNDATION MAPS.


Description	Drawing No.
Pier No. 1	FPII-1, FPII-2
Pier No. 2	FPII-3 thru FPII-7
Pier No. 3	FPII-8 thru FPII-10
Pier No. 4	FPII-11 thru FPII-13
Pier No. 5	FPII-14 thru FPII-17
Pier No. 6	FPII-18 thru FPII-22
Pier No. 7	FPII-23 thru FPII-27
Pier No. 8	FPII-28 thru FPII-31
Pier No. 9	FPII-32 thru FPII-36
Pier No. 10	FPII-37 thru FPII-40
Pier No. 11	FPII-41 thru FPII-44
Pier No. 12	FPII-45 thru FPII-48

INDEX (Cont.)

Description	Drawing No.
Pier No. 12, Sill	FPII-49 thru FPII-51
Training Wall	FPII-52 thru FPII-55
Bay No. 1, Cutoff Trench	FPII-56
Bay No. 2, Cutoff Trench	FPII-57
Bay No. 3, Cutoff Trench	FPII-58
Bay No. 4, Cutoff Trench	FPII-59
Bay No. 5, Cutoff Trench	FPII-60
Bay No. 6, Cutoff Trench	FPII-61
Bay No. 7, Cutoff Trench	FPII-62
Bay No. 8, Cutoff Trench	FPII-63
Bay No. 9, Cutoff Trench	FPII-64
Bay No. 10, Cutoff Trench	FPII-65
Bay No. 11, Cutoff Trench	FPII-66
Bay No. 1, U/S Face	FPII-67
Bay No. 2, U/S Face	FPII-68
Bay No. 4, U/S Face	FPII-69
Bay No. 5, U/S Face	FPII-70
Bay No. 7, U/S Face	FPII-71
Bay No. 8, U/S Face	FPII-72
Bay No. 9, Plan View	FPII-73
Bay No. 9, U/S Face	FPII-74

INDEX (Cont.)

Description	Drawing No.
Bay No. 10, U/S Face	FPII-75
Bay No. 11, U/S Face	FPII-76
Gate Bay No. 1, Foundation	FPII-77
Gate Bay No. 2, Foundation	FPII-78
Gate Bay No. 3, Foundation	FPII-79
Gate Bay No. 4, Foundation	FPII-80
D/S Stilling Basin, Plan View	FPII-81
Gate Bay No. 5, Foundation	FPII-82
Stilling Basin No. 8	FPII-83
Geologic Cross Section - Pier No. 1, Bay No. 1	FPII-84
Geologic Cross Section - Pier No. 2, Bay No. 2	FPII-85
Geologic Cross Section - Pier No. 3, Pay No. 3	FPII-86
Geologic Cross Section - Pier No. 4, Bay No. 4	FPII-87
Geologic Cross Section - Pier No. 5, Bay No. 5	FPII-88
Geologic Cross Section - Pier No. 6, Bay No. 6	FPII-89
Geologic Cross Section - Pier No. 7, Bay No. 7	FPII-90
Geologic Cross Section - Pier No. 8, Bay No. 8	FPII-91
Geologic Cross Section - Pier No. 9, Bay No. 9	FPII-92
Geologic Cross Section - Pier No. 10, Bay No. 10	FPII-93
Geologic Cross Section - Pier No. 11, Bay No. 11	FPII-94
Geologic Cross Section - Pier No. 12	FPII-95



PART I
PHOTOGRAPHS

 Cut-off trench, Gate Bay Mo. 1, View from D/S, Ky. Side, Looking toward U/S face. 12 Nov 76



 Cut-off trench, Gate Bay No. 1, View from Pier 1. 12 Nov 76



3. Cut-off trench, Gate
Bay No. 2, View from
Pier 2, Facing Pier 3,
3 Dec 76




4. Cut-off trench, Gate Bay No. 4, View from Pier 4 facing Kv., Showing downstream face. 8 Dec 76




5. Cut-off trench, Gate Bay No. 4, View from Pier 4 facing Kv. showing upstream face. 8 Dec 76



6. Cut-off trench, Gate Bay No. 5, View from Pier 6 showing foundation cleanup. 16 Mar 77



7. Cut-off trench, Gate Bay No. 5, Solutioning in downstream face 17 Mar 77



8. Cut-off trench, Gate Bay No. 5, View of healed joint in foundation.
18 Mar 77



9. Cut-off trench, Gate Bay No. 7, Foundation. 24 May 77



10. Cut-off trench, Gate Bay No. 7, Solution cavity in downstream face. 24 May 77



11. Cut-off trench, Gate Bay No. 8. View from Pier 9. 7 Jun 77



12. Cut-off trench, Gate Bay No. 9, Downstream face. 23 Jun 77



13. Cut-off trench, Gate Bay No. 9, View from Pier 10 looking toward Pier 9. 23 Jun 77



14. Cut-off trench, Gate Bay No. 9, View from Pier 10 looking at upstream face. 23 Jun 77



15. Cut-off trench, Gate
Bay No. 10, View from
Pier 10 towards Pier 11.
30 Jun 77



16. Cut-off trench, Gate Bay No. 10, View from Pier 11, Looking at unstream face. 30 Jun 77



17. Cut-off trench, Gate Bay No. 11, View from Pier 12. 30 Jun 77



18. Looking down stilling basins from lockwall to Ky. Note Overbreak. 12 Jun 78

NOTE: Portions of U/S faces of Gate Bays can be seen on Pier foundation photographs.



19. Downstream pre-split face, Gate Bay No. 1, Sta. 0+49.5D, Sta. 72+60S $^{\pm}$, Elev. 260-270 $^{\pm}$. 13 Dec 77



20. Downstream pre-split face (Sta. 0+49.5D), Gate Bav No. 2, Sta. 73+40S to $73+70S^{\pm}$, Elev. $260-270^{\pm}$. 19 Dec 77



21. Solution channel in 10' strip, Gate Bay No. 2, Sta. 72+50S to 72+60S, Sta. 0+39.50 to 0+49.50, Looking upstream. 19 Dec 77



22. Clean-up in 10' wide section, Sta. 0+39.5D to 0+49.5D, Stilling Basin No. 3, Mudseam at $74+25S^{\pm}$. 21 Dec 77




23. Downstream face, Stilling Basin No. 5, Illinois 1/4 of bay, Undergoing final clean-up, Bottom Elev. 253.5[±]. 5 Apr 78



24. Upstream face, Gate Bay No. 5. 31 May 77



25. Looking downstream into Stilling Basin No. 5 from tainter gate.
Solutioned area on right prior to removal. Trench through rest of bay later cleaned out and filled with dental concrete. 4 Apr 78



26. Solution channel, Center of Stilling Basin No. 6, Sta. 78+255½: 0+13.50 to 0+46.50, Looking toward Illinois. 29 Apr 78




27. Solution channel, Stilling Basin No. 6, Illinois side and downstream of Pier 7. 3 May 78




28. Solution channel Stilling Basin No. 6, Ky. Side of Pier 6, 27 Apr 78



29. Stilling Basin No. 7, Looking toward Kv. 8 May 78



30. Stilling Basin No. 8, Solution channel, View from Pier 8. 31 May 78



31. Stilling Basin No. 8, Showing rock "bridge" over solution channel after excavation, Looking downstream. 31 May 78



32. Stilling Basin No. 9, Hole in upstream III. corner, Due to overbreak and solution channel. 31 Jun 78



33. Kentucky half of Stilling
Basin No. 9, Low area just
downstream of ogee section
which was placed separately
to level foundation for
anchor rod installation.
15 Jun 78



34. Stilling Basin No. 10, Looking from Pier 10 at installation of rock anchors. 30 Jun 78



35. Stilling Basin No. 10, Solution area, Bottom Elev. 252±, Sta. 83+11S to 83+28S and 0+41D to 0+47D. 10 Jul 78




36. Stilling Basin No. 11, Looking from Pier 10 towards Ky. 30 Jun 78




37. Pier No. 1, Presplit line looking downstream from Sta. 1+270. 25 Aug 76





38. Pier No. 1, Rock face jut downstream of cut-off trench, Kv. side. 13 Oct 76






40. Pier No. 1, Upstream face. 9 Oct 76






42. Pier No. 2, View from inside looking at upstream rock face. 26 Oct 76



43. Pier No. 2, downstream face. 26 Oct 76



44. Pier No. 2, Illinois side in area of cut-off trench. 15 Oct 76





46. Pier No. 3, View along center line showing Ky, side prior to form work. 16 Oct 76



47. Pier No. 3, View from inside excavation showing downstream rock face. 20 Oct 76




48. Pier No. 4, Unstream Ill. corner. 18 Nov 76



49. Pier No. 4, View from downstream III. side showing downstream face and Ky. corner of excavation. 18 Nov 76



50. Pier No. 4, Kv. side just upstream of cut-off trench. 18 Nov 76





52. Pier No. 5, View from downstream end showing excavation progress.

8 Dec 76






54. Pier No. 5, View of Mid section of Kv. side. 10 Dec 76

(Unstream and downstream sections very similar)




55. Pier No. 5, View of mid-unstream III. side. Bottom Elev. 225±. 10 Dec 76



56. Pier No. 6, Upstream III. corner of pier. 18 Feb 77





58. Pier No. 6, Downstream Kv. side. 22 Feb 77



59. Pier No. 6, Middle of unstream face.
18 Feb 77


..;



60. Pier No. 6, Overbreak on downstream end of Pier 6. Ruler at approx. neat line. View from Ev. side. 22 Feb 77



61. Pier No. 7, View from upstream end looking at downstream end, $10~{\rm May}~77$



62. Pier No. 7, View from III. side looking at Ev. side. Note solutioning in foundation floor. 10 May 77




63. Pier No. 7, View of upstream III. side. Solutioning at founding Elev. 250^{\pm} . 12 May 77



64. Pier No. 7, View from Ky, side showing Ill. side just upstream of cut-off trench. 11 May 77






66. Pier No. 8, Looking downstream at III. face and cut-off trench in Gate Bay No. 7. 2 May 77



67. Pier No. 8, Looking downstream at Kv. face and cut-off trench in Gate Bay No. 8. 2 May 77



68. Pier No. 8, Upstream face. 4 May 77



69. Pier No. 8, Close-up of solution channel in upstream face. 4 May 77



70. Pier No. 8, View of Kv. face just downstream of cut-off trench. 4 May 77



71. Pier No. 8, Close-up of solution channel in Ky. face just downstream of cut-off trench. 4 May 77



72. Pier No. 10, View along Ill. side, Looking downstream. 2 May 77



73. Pier No. 10, View from upstream Ill. corner showing Ky. side. 2 May 77



74. Pier No. 10, View from downstream end showing upstream face. Concrete at Elev. 250. 2 May 77



75. Pier No. 10, View from upstream end showing downstream face. Concrete at 250. 2 May 77



76. Pier No. 11, View from upstream Ky, side showing III. face and cut-off treanch in Gate Bay No. 10, 31 May 77



77. Pier No. 11, Solution channel in downstream 111. corner of excavation. 28 May 77




78. Pier No. 11, View from downstream end showing upstream face.
28 May 77



79. Pier No. 11, View of solutioning at Elev. 246 bedding plane in upstream face. 27 May 77



80. Pier No. 11, View from upstream III. corner showing Kv. face and cut-off trench in Gate Bay No. 11. 31 May 77




81. Pier No. 12, View from just downstream of cut-off trench showing Ky, side. Pre-split on 6"cc. 6 Jun 77



82. Pier No. 12 and Training Wall, View from upstream end looking downstream. 14 Jun 77



83. Pier No. 12 and Training Wall, View from downstream end looking unstream. 7 Jun 77



84. Pier No. 12, Solution channel and joint in upstream face, Ull. corner at left. 12 Jun 77




85. Pier No. 12, Joint in upstream face of pier. 14 Jun 77





86. Training Wall, View of rock conditions in Kv. face, Bottom Flev. 240^{\pm} . 6 Jun 77





PART II FOUNDATION MAPS

















PIER 2

FPII-4







Ky.

D/S END PIER 2 Sta. 0+13.54 THIN - BKN. N.D.E BKA FRAC.

MED. BOD.

OP J SLUMB

CALL

STEED SLUMB

CALL

CALL

CALL


STEE


S


MOL


5 END PIER 2

ILL.










FOUNDATION FLOOR

′)



DIS END BKN. BEYOUT PRESPLT LINE

255 BKN. WEA. D. CHTY IS

WEA BDD. PLN.

258

258

258

CHTY.

SLIMP

249.7

245

KY.

PIER 3 D/s End


20 Oct.76 FPII-

506+0 0+805 300_ 290. 280 _ 270_ 260_ FORM WORK TO STA. BDD. PLN. 250 _ 240 _ U/S

PIER 3


KY SIDE

0+505 0+205 0+605 BKN. D. LS. SOL. CHTY. IS. 250.1 HIGHTY WEA. RES. MA. GRAVEL 0+13.5 U D/S





PIER 4

▲ SMC 34




FOUNDATION FLOOR






FPII - 12




5/A. 0+13.5 U


260_



U/S FACE PIER 4 Sta. 1720.5 U




DIS END PIER 4




U/S FACE PIER 4 Sta. 1720.5 LI


FP II - 13



PIER 5




FOUNDATION FLOOR




P/S END 0+13.5U PIER 5 EL. 270 -EL 260 -WITTE THE KALK LS. EL. 250 -THIN BOD CHTY., DENSE LS. (SHY.) . BOD PIN. Sigh D. T. - MED BOD SW. LS. EL. 240 _ 3. 18/+ HOR, CALC, 5755. STYL - CHTY. STYL. STYL. - 5+YL RR. CHT. DK. SR. CL-SH. COA. BDB. PLN EL. 230 _ - CHTY. STYL. POL. 15.


EL 220 _


FPII-15




ILL. SIDE









FP II - 17




PIER 6



FOUNDATION FLOOR




V/s FACE PIER 6




DIS FACE PIER 6


245_




KY SIDE


PIER 6







PIER 6









PIER 6




PIER 7






MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS 1965 A




BY	DATE	SUBJECT				
	79+20 \$	\$ 01+62	\$ 00,62	\$ 06-82	78480 \$	
300) <u> </u>					
290					! ! !	
. 280)				 	
270	1	3	3 - PL -	اب با	1	
260		Sol			BKI A	
250	S. 25.67 S.	= D/3	SEND	The same	7.63	

BY	DATE	SUBJECT	SHEET NO OF
CHKD. BY	DATE		JOB NO




PIER 7




and the state of t

The state of the s




U/S


PIER 7




KY. SIDE




 \mathcal{F}



PIER 8




FOUNDATION FLOOR




PIER 8


JOB NO 310_ 300_ 290_ 006. LS. MASS. 280_ 9 5-78-E St. St. F, XYUN V.F. XYLH., Y. CHTY. 270 SOL F, XYLM, SL. CHTY. 260_ 250_ BDD. PLN. PIER B 240 _ U/S

SHEET NO .







FPII- 31



PIER 9





FOUNDATION FLOOR




PIER 9

CHKD. BY	DATE	SUBJECT			SHEET NO CF
	81+705	81+605	81+505	81+408	805-18
	1				_ 290
	} 				280
•	1	۷.35-۴			270
	E XY	J. J	W CENTRY	OL) KILM	
24 <i>5</i> ,	Y. F. XYLM	CATY. WA	TER SO	DENSE CHTY.	WATER 250 S-WEN. BOD. PUNI. 15
	(E) V	^ ^ ^ /	(X " X " X		<u> 240</u>






PIER 9




U/S

KY. SIDE





D/S



and the second second


- 1





\$06+28 \$ 08+28 83+00\$ 300 T/R @ 5ta. 1+25 U 290 cut beach. 280 STYL. Ldd. pln. of wed. 270 becoming Vichty @ 27/± ChT. nod. 501. 61d. Pln. 260 XY/n. LS. 6dd pln. 250 XYIA. Chty. n — Wed. 611. Pln. 0 — xyln. 2449 xyln xyln. LS. D/Send PIER 10

FPIT- 38



0+80


N06+0


1.000

1+10 U

1+20N


Cut. Off TRench.






KY SIDE

PIEF. 10





XYIN/Chty

XYIN/Chty

XYIN. Chty.

Wez. bdd. pln.


XYIN. Chty.

M. Wez. bdd. pln.


M. Wez. bdd. pln.

M. Wez. bdd. pln.


PIER 10




PIER II




FOUNDATION FLOOR
FOUNDING ELEV. 241



PIER II




PIER II





PIERII

00+0 000+1 000+1 000+1 000+1





PIERII ILL.







PIERII






85..5JS_









280 _


270 _




ILL SIDE




FPII-47










U/S

PIER 12 S'LL


0+43 = 1



0+4255 85+53⁵⁴S

PIER 12 SILL

FOUNT AT IC




U/S

PIER 12 SILL

D. Chry. WEZ. bld. PlN

PIER 12 SILL KY. SIDE




PIER 12 SILL


D/S

001+0

5-10.6

SILL ILL SIDE






U/S

TRAINING WALL-I


1-9




ING WALL-I

FOUNDATION FLOOR

FPII-52




7/S ENT TFAILL - W/ ...



DIS END Alli - WI -

FPII-53



T- NING W

Action vicility of the second second

TE-NING WALL.

7

0+50D 0+50D 0+50D 0+50D 1+00D 1+00D


275_

257_


250_

240_

U/S KY. SIDE



TRAINING WALL



TRAINING WALL

ELEV. 260_ PROFILE 250. 240_ PIER 2


BAY NO. 1

CUIDE

50L-07. N-28-E THIN-MED BOD. 5-Y XYLN. LS. C bkw 6 1 EL GR.CL. /RO FR. B. T. 6.7. 2.3. 5 2.657 2.70 CALE. BJC S E14.7, 255. 1 CUIDEF TE- NOH 10. 1

FPII-56

ELE 1. 250_ V FRAC (BIASTING 200 Pier 3 PLAN VIEW しかて PR0=1-E 5/0 7560 ELEV CUTOFF BAY NO. 2 FOUNDING ELEV 250



CUTOFF TRENCH

2


DATE I DEC 1976

1

ELEV. 260_ PROFILE 240-Pres 4 PLANSOY 077 [£] 250 Slope FACE PROFILE SA 092 EFEN

BAY NC. 3

CUTOFF




CUTOFF TRENCH

ELEV. 100_ D/Ś 210_ PIER5PLANE C42 = 5 + P97. d. Chty. LS. BT1 = Odd 3/1

BAY NO. 4

CUTCER




CUTCFF TRENCH

FPII - 59

ELEV. 260_ VIEVX CtZ ETIFOUR Phylikey & PRESENT 5/1 CE3 BAY NO. 5

the state of the same of the same of



CUTOFF THEHICH

ELEV. 260_ CKHEK TO HITS 1/S w) w/ fir mod seams. 227-501 6h. 250_ 1.301. ch. hd. solid foss. Ls. PLANIS VIEW® 1.1 052-660:17E Poch on 3-1510pe

> - SEO EFEN

3/1

BAY NO 6

CUTO

To 11 Jts

Y has mud seems.

51-Ch.

Ol. Ch. 1

BKN. BOTH HOR TVERT ON JTS.

MOST EREIKS HAFFER TR. JRIII
170/05 IN BOTOM FROM FRESHIT
BRK. BACK 6' AT FOTOM TO 4'
9 260.0 AFFERRS TO be OJEKSHOT


Les of the second of the secon

Stor Roch on 3-1510pe

NO 6

CUTOFF TRENCH

ELEY. 260 PROFILE 240 _ PLANT PZ X St. bdd pln. **DBOEIFE** SA 7560 ELEV Founding E/EV. 250. BAY NO. 7 CUTOFF





0. 7 CUTOFF TRENCH


E_EV. 260_ PPD= 240 PLANT PROF.LE 34 S-24-E II (ALL 197.5


25 Holes OVER DRIVED 8'

BAY NO. 8

CUTO

AREA WARREN/ TACK FRANCES To mire Wisth N-303-6 JT.






BAY NO. 8

CUTOFF TRENCH Fou 249

ELEV 5-303-W. 27'C. HIL. JT. 260. PROFILE PLANY Street 045<u>3</u> 11 7-88 N-052 371 108d S/A 7560 ELL V

BAY NO. 9

CUTO




YNO. 9 CUTOFF TRENCH Fox 245

FPII: 64


ELEV. 260_ PROFILE 250-PLAN \$ 540 7220 PROFILE 5/1 09Z_ ELEV CUTO


BAY NO.

10



Y NO. 10 CUTOFF TRENCH F- 243





NO 11 CUTOFF TRENCH F- 243

FP II- 66

	71+735	71+20	< 00 - 1	200-22		7.55 + 52.7		773.400
300_	ţ					roin Exporisa Westreped		
290_	!				n re	rtirefacelo	og in Siay	M. TER
<u> </u>	1		2	4				ø
270_	9 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	Covered w	A A A A S S S S S S S S S S S S S S S S	TO TO AC	Carina	- 1. A.A.	7.5	mc
260_	7.7.	ERV. ROCK		JOCIETY TO		Y . 19 = 3	<u> </u>	T
250_	+ 1/4 53							
	! !				2	: · I U	S =A([1]

٧.


72:25 5

note all poin exposed between piers land a very westhered which though straing out in the first poors very mound like a continual feature.

Cavins

VENTON

BAYIUS FACE



508157 25-40 S S (54 : ?) 72.500 ,,₄₄/, 361.0 Sol. Chamel. 13 + 8 3. 54 S DIE! BAY Z

1)

75+805 75+405 502+51 76.000 75+55. 290_ 230__ 270_ N-22-E Sol. CHANNEL. 260_ 75+48.54 250_

Sir - PROFILE ALON

504492 501+92 76+305 75+805 502+91 76:03 75+55 284.0 233.1 M. bdd. Thin mes 6.88. PID. T dense Chty. - - 644 FIN. ×y/λ. had. FIN. Med. bad. FIN 76134.543


327 - PROFILE ALONG STA. 1+2712 U/S FACE

							502+22	シハケーピア
300_	į	1 						
290_	5885 1			3	ځ د رو.	Marie Barrer		, 'd'S .
230 <u>_</u> ***dk:0	We ?. bdd plw S S Lv. bdd. Flw	. 25.	- V.F.XVIA.	dd 6"-15" Thick	chty	BKN.		Tred. 61 V shry. Ls.
270_	bdd. PIN. bdd. PIN.	~ Shry		_ER. Sd. JT.	5-39-E Sev. Hid Ver Aid Ce 396	N. 22. E G. S.	-rid.	
260_	ا ; سي ا			····· .			n –	
250_	7, EK 5 70+73,54							
	,	3:	· Y . É		.E	かっこか)

٠.

77+305 77.50 bdd. 6"-1.5" Thick PKN. T. med. bds. V. ch-y. Ls. --- d. V. F. XYIN LEAK 142 4 = 125 N-23 E GR. SI. GL. FI 21. FI wed. _EQ. 501. 5-39-E Sev. hid Fed. 6 Fid. - 13 - 23 - W 1.18.45 777 54 545 ALDN - 1. 1. 1. 1. 1. 1/2 - - 2 POSTLE

FPII - 70




5-73-€ 34.

BAY 7 USFACE

1 PIER 3

FPI - 71





VIEW - dense - MANY V. BYN. OCC. LS.

VIEW - dense - MANY V. BYN. OCC. LS.

VIEW - dense - MANY V. BYN. OCC. Cht.

V. Chty.

V. Chty.

St. Chty. Chty.


St. Chty. Chty.

St. Wed - S-73-E JT.

EAY 8 US FACE

Pier 9


7




08-17 206.65. V. XYIN. occ. Chty ST. 5T. F. XYIN. LS. V. Chty.


PIER 9

BAY 9 WS FACE




FIER 10








MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS 1965 A



10 U/S FACE

PIER 11

06:08





84.60 84.70 94.70 85.00 85.00

ool. Thexe.


BAY II U/S FACE


PIER 12







FPII-77








bkn, blky, for breaks; springing on sts.
no pre-split holes visible
unable to map




FOUNDATION GATE BAY 3

for breaks; springing on its re-split holes visible unable to map - EL.270



UNDATION GATE BAY 3

Notes and the state of the stat



FOUNDATION
GATE BAY 4

HIGH T

T W/ Cherty T
/ayers

1 75+78:54\$

FOUNDATION
GATE BAY 4

O+49.5D

O+39.5D

EP-4

STA 75+28.54\$

ل

ben fell back

To parallel ST.

2-3'

most pre-split hale visible

fine Grained 5ilty.45 . hd. gn

X-line LS, nd, Ge.

6-10

FACE VIEW

DIS PRESPLIT LINE

STILLING BASIN 5

PLAN VIEW D/S STILLING BASIN mud presplit

fine Grained 5ilty, L5 · hd gn Some ut. JTS. above 4-5' spaces VT. TOE

— EL.270

BP. /-4"/W) w/ clay flug

X-line LS, hd, Ge.

PEW JTS.

— 760

VIEW ESPLITLINE ING BASIN 5


0+49.50


0+39.50

LAN VIEW STILLING BASIN

2

FPIT-81






0+47.50 Bris sidismooth P.9 8133.518 STILLING BASIN #8

hd, 50/7 50 45. Berd Wid, Smooth. +172 ro 31 531 4.2 EP In cot hd. E. ig. -re room son re 0+13.50 F-3 10w bischy ! Hac. ING BASIN #8 FP II - 83

•


i	3 1	:						İ
260	LOCK WALL	509+1	201+17	7/+ 805	506+//	500+22	72+105	
		_ PIER		·				
250		T T T, JETX: VA	nd ha. ze. 7 St. 5:7	xyiri 25	. - - -	8 ∵. I ↑	SR C. YYIN. STYl	Yyin:
	1	•	18.36. 484. 15. mod. ab na, 2 n. 8771. 51. 001.	d. 15.	-		bod pm. mod ha GR. Bonse mod ha.	
_		med. mcR.Cl	es mod hd. (3K. S. Dok. Shm	t		51 (i-ch;	, 5, 7. .yin , 00 . y, LS, 1: 03: 66 - 2 1. Váy, y;	, _
-		1 -ce.cu				نون ب		
		- gg c)					71	
2		24 CI	i.			عد - عد -	cl	
		JK 9750	r Shits No. Fr. Mica.			د . تا	ct ice mad be sym. arich fid	
		229.2				2243		


<u>.</u>,




•

FPII-84
GEOLOGIC Cross
SECTION
PIEN LBAY !








٠.


١.





7

SECTION PIER 3 BAY 3 074+90S 75+605 75+405 500+51 754 205 754505 75 1305 75+/05 PIER 4 bdi ... --- 30014 ; 31 · d Sei a ≜ tae (r. 16 (7) 57. <u>1</u>

<u>.</u>,







PIER 6

76


. 5

. -- <u>.</u>

- - + 6.7

. 0.7


B/# 224



50818C) 79+1:05 202165 79+305 79+205 244005 73+105 78,905 2 55 37.13 15 med 7 15 xyll 2 17 xyll 10 (C22)

٠,

٧.



•

(5) (80+10s 80+52 80+305 80+40E 801505 801205 30+.0-80+805 FC-18 Laxenge here LE MOLLENG TR. E & STATE 5. 0 53 F3 220 25. 11.13. ha se 1 H .

٠.

To the Roll

260 BS4308 BS4408 BS440

Ļ,


Fig. and FM

OF 11 Fr. Ab

V.F. Xyr

220

B/H 217.6



844/2. 3444/2. 3444/2. 3445/2.

١,

10 ----

12.0 22.0

J. 6. 4. 07. (42) # (26) 84+705 19+30_ 3:+60 84150 DEL MIL (POSS PIER II BAY II

Ş.

B/™ 28 €

85+205 36.5158 361400 260 Pier 12 250 2+7 23. Con Shi Li Presar An Shi Kalini Static Gusti Follows 120

5/H 2 ? ? 308+38

308+38 85+705

80+30c

5

5 = 13 C = 15 Ser 12-

′}

